



JON M. HUNTSMAN, JR.
Governor
GARY R. HERBERT
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report
Minerals Regulatory Program

Report Date: June 23, 2005

Supervisor 

Mine Name: Century Mine
Operator Name: Al Dart

Permit number: M/003/048
Inspection Date: June 14, 2005
Time: 5:00 pm – 5:30 pm

Inspector(s): Lynn Kunzler
Other Participants: Dave Morris (land owner)
Mine Status: Inactive – Requested inspection to close file

| Elements of Inspection | Evaluated | N/A | Comment | Enforcement |
|---|-------------------------------------|--------------------------|-------------------------------------|--------------------------|
| 1. Permits, Revisions, Transfer, Bonds | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 2. Public Safety (open shafts, adits, trash, signs, highwalls) | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3. Protection of Drainages | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 4. Explosives, magazines | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 5. Deleterious Material | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 6. Roads (maintenance, surfacing, dust control, safety) | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 7. Concurrent Reclamation | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 8. Erosion Control | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 9. Demolition | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 10. Backfilling and Grading (trenches, pits, roads, highwalls, shafts, drill holes) | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 11. Water Impoundments | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 12. Soils | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 13. Revegetation | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 14. Air Quality | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 15. Other | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Purpose of Inspection:

Operator requested inspection to close file.


Inspection Summary:

1. This area was inactive. While operator has requested closure, reclamation has not been completed.
2. A slot approximately 30 feet wide and up to 40 feet deep and about 100 feet long has been excavated in an attempt to get a clean face into the old tunnel. The cut walls on this slot are near vertical and are starting to spall. Because this site is on private property (and behind locked gates), safety to the general public is not a major concern. However, the landowner does not feel that the area is stable or safe for his livestock.

Inspection Date: June 14, 2005; Report Date: June 23, 2005
Page 2 of 2
S/003/048

7. While the Operator has requested this inspection to close the file, it appeared that there has been no attempt to perform any reclamation work. The site needs to be reclaimed before the Division closes this file.
15. The Operator still has trailers, a front end loader and other miscellaneous equipment on site.

Inspector's Signature



Date: June 23, 2005

LK:jb

O:\M003-BoxElder\S0030048-Century\inspection\insp-06142005a.doc